




Go to Start menu> Control Panel




Go to System > properties




Go to Hardware Tab> Device Manager




Check which port is detected by USB driver.




Go to Start Menu> Accessories> Communications> HYPER TERMINAL



Type Here Connection name (any Name can be typed) and click OK




Then Select COM Port that have been detected in device manager



Then Click OK, following Screen appears

Here input data accordingly in the following fields



Click Apply and Then OK Now Start Typing on The Blank Screen and it displays the data only on VFD.