



After USB Driver Installation go to My Computer Properties




Then go to Device Manager Then check the Com Port







Then Go To Start > Programs > Accessories > Communication > then Click Hyper Terminal



Enter any Name to create a Account



Then Click OK




Then Select Com Port and Click OK

Then the Following Screen Starts, Set The Parameters of VFD-860 here according to the Parameters Shown on the VFD-860 Display Screen

Then Click Apply > ok



After this you can see the timer at the left corner of the hyper terminal screen

As connected \_\_:\_\_:\_\_



Then Create a simple Notepad file of the multiple alphanumeric keys,

Save it on the desktop



As you select the file, the matter in the file is started displaying on the screen of the VFD-860.